UNCLASSIFIED

AD NUMBER

AD366705

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited


FROM:

Notice: Release only to U. S. Government Agencies is authorized. Other certified requesters shall obtain release approval from Director, Defense Atomic Support Agency, Washington, D. C. 20301.

AUTHORITY

DSWA ltr., 10 Apr 97; DSWA ltr., 10 Apr 97

THIS PAGE IS UNCLASSIFIED



BUREAU OF SHIPS GROUP

TECHNICAL INSPECTION REPORT

U. S. GOVERNMENT : FROM DDC. Gramme

This document contains information associates the lational figure to an unauthorized for the formation of the matter to an unauthorized for the prohibited by late 3

Approved:


F. X. FOREST, Captain, U.S.N.

SECRET

USS NEVADA (BB36)

Page 1 of 139 Pages

CONFIDENTIAL



CONFIDENCIA




BA-CR-196-151-11. View from slightly off port bow before Test A.

SECRET

Page 2 of 130 Pages


DENTIN USS NEVADA (BB36)



AA-CR-227-50-122. View from dead ahead after Test A.

Page 3 of 139 Pages

USS NEVADA (BB36)



BA-CR-196-151-10. View from off port bow before Test A.

Page 4 of 139 Pages


UŞS NEVALA (BB36) 9545



AA-CR-227-91-75. View from off port bow after Test A.

Page 5 of 139 Pages

USS NEVADA (BB36)



BA-CR-196-151-15. View from off port beam before Test A.

Page 6 of 139 Pages

USS NEVADA (BB36)



AA-CR-227-91-74. View from off port beam after Test A.

Page 7 of 139 Pages

USS NEVADA (BB36)

95 4 5



BA-CR-196-151-9. View from off port quarter before Test A.

Page 8 of 139 Pages


USS NEVADA (BB36)



AA-CR-227-91-73. View from off port quarter after Test A.

Page 9 of 139 Pages


USS NEVADA (BB36)



AA-CR-227-50-118. View from stern after Test A.

Page 10 of 139 Pages


USS NEVADA (BB36)



BA-CR-196-151-13. View from off starboard quarter before Test A.

Page 11 of 139 Pages


USS NEVADA (BB36)



AA-CR-227-50-119. View from off starboard quarter after Test A.

Page 12 of 139 Pages


USS NEVADA (BB36)



BA-CR-196-151-16. View from off starboard beam before Test A.

Page 13 of 139 Pages


USS NEVADA (BB36)



AA-CR-227-50-120. View from off starboard beam after Test A.

Page 14 of 139 Pages


USS NEVADA (BB36)



BA-CR-196-151-12. View from off starboard bow before Test A.

Page 15 of 139 Pages

USS NEVADA (BB36)




AA-CR-227-50-121. View from off starboard bow after Test A.

SECRET

Page 16 of 139 Pages

USS NEVADA (BB36)



AA-CR-62-1859-5. Forward superstructure from starboard.

Page 17 of 139 Pages

USS NEVADA (BB36)



AA-CR-80-1909-12. Part of radar antennae at frame 42, starboard side on the upper deck.

Page 18 of 139 Pages

USS NEVADA (BB36)



AA-CR-79-1935-11. Looking to starboard and slightly forward on forward AA defense station at broken radar drive unit. Unit has fallen from S.K. radar.

USS NEVADA (BB36)


Page 19 of 139 Pages



AA-CR-80-1909-10. Looking aft at forward superstructure from starboard side.

Page 20 of 139 Pages


USS NEVADA (BB36)



AA-CR-80-1909-9. Looking aft at forward superstructure from port side. Note uncharred shadow outline of tank on wood deck covering.

USS NEVADA (BB36)


Page 21 of 139 Pages



AA-CR-80-1900-3. Forward tripod, remains of starboard yardarm.

Page 22 of 139 Pages

USS NEVADA (BB36)



AA-CR-80-1900-4. Forward tripod, view looking forward at wreckage of starboard yardarm. Main member, truss and forward strut.

USS NEVADA (BB36)

Page 23 of 139 Pages



AA-CR-82-1830-9. Starboard 36" searchlight carried from platform and lying on superstructure deck in way of starboard access to upper deck at frame 68.

Page 24 of 139 Pages

USS NEVADA (BB36)



AA-CR-80-1830-6. Looking aft and to starboard on 36" searchlight platform on forward tripod at remains of searchlight. Note broken trunnion arms.

USS NEVADA (BB36)

Page 25 of 139 Pages



AA-CR-79-1935-10. Looking up, aft, and inboard at wrecked port searchlight or searchlight platform. Forward A.A. defense station in foreground.


USS NEVADA (BB36)



AA-CR-80-1911-6. Foremast structure looking forward from mainmast.

Page 27 of 139 Pages

USS NEVADA (BB36)



AA-CR-82-1830-7. Inter-communication boxes on the forward AA defense station, looking forward at units partially dislodged from their mountings.

USS NEVADA (BB36)



AA-CR-80-1911-11. Main battery and fire control station looking to port at frame 67. Note damaged after bulkhead of bridge urinal.

Page 29 of 139 Pages

USS NEVADA (BB36)



AA-CR-80-1911-12. Main battery and fire control station looking aft at after port corner of bridge urinal from about frame 66. Note stack in background.

USS NEVADA (BB36)


Page 30 of 139 Pages



AA-CR-65-1742-7. Looking forward at blast damage to port wing of navigation bridge and underside of open bridge wing.

Page 31 of 139 Pages


USS NEVADA (BB36)



AA-CR-80-1911-10. Navigating bridge level, port side looking forward and from catwalk at damaged bulwark.

USS NEVADA (BB36)

Page 32 of 139 Pages



AA-CR-80-1911-9. Signal bridge at frame 65 looking to port showing damage to transverse bulkhead 65.

USS NEVADA (BB36)


Page 33 of 139 Pages



AA-CR-175-2155-2. Superstructure deck at frame 67 looking to starboard at after face of forward superstructure and forward part of stack.

Page 34 of 139 Pages

USS NEVADA (BB36)



AA-CR-80-1910-6. Looking forward at damaged port gun inboard bulwark on superstructure deck at frame 57. After edge of bulwark has been torn loose from deck and moved forward and inboard. Note also screen on turret ventilation trunk bellied downward.

SECRET

USS NEVADA (BB36)

Page 35 of 139 Pages



AA-CR-79-1935-9. Superstructure deck deflection at frame 50 under the overhang of turret No.2. Looking to starboard and slightly forward.

USS NEVADA (BB36)

Page 36 of 139 Pages



AA-CR-80-1910-5. Superstructure deck, deflection at frame 50 under to overhang of turret No. 2, looking forward and to port.

USS NEVADA (BB36)


Page 37 of 139 Pages



AA-CR-80-1910-7. Superstructure deck looking aft and outboard from frame 58 port. Railings and gutter strips were damaged by ships force removing equipment from fore-top.

USS NEVADA (BB36)

Page 38 of 139 Pages 9545



AA-CR-80-1910-2. Looking aft along the starboard side of the upper deck from frame 63.

Page 39 of 139 Pages


USS NEVADA (BB36)




AA-CR-175-2154-11. Looking aft along starboard side of superstructure deck from frame 62 showing damage to the handrail.

Page 40 of 139 Pages

USS NEVADA (BB36)






AA-CR-175-2154-10. Looking aft along port hand rail of superstructure deck from frame 62.

Page 41 of 139 Pages


USS NEVADA (BB36)



AA-CR-80-1910-8. Looking aft and to starboard from frame 65 on superstructure deck at damaged stack and deck dishing

USS NEVADA (BB36)


Page 42 of 139 Pages




AA-CR-80-1910-12. Looking to starboard and forward on the super-structure deck from frame 78, showing damage to stack.

Page 43 of 139 Pages

USS NEVADA (BB36)



AA-CR-80-1910-11. Looking to port and slightly forward on the superstructure deck from extreme starboard at frame 78. Besides damaged stack, note magnetic compass binnacle, removed from forward side of mainmast structure when clearing damaged mainmast structure.
USS NEVADA (BB36) Page 44 of 139 Pages



AA-CR-62-1859-4. Foremast and mainmast from starboard.

Page 45 of 139 Pages


USS NEVADA (BB36)



AA-CR-80-1900-6. Lower section of broken Charlie Noble and damaged stack looking forward, down, and to port.

USS NEVADA (BB36)


Page 46 of 139 Pages



AA-CR-80-1910-9. Superstructure deck looking athwartships from the port side at frame 74 showing damage to the deck and the stack.

Page 47 of 139 Pages

USS NEVADA (BB36)



AA-CR-80-1910-10. Superstructure deck looking athwartships from the starboard side at frame 74, showing damage to the deck and the stack.

USS NEVADA (BB36)

Page 48 of 139 Pages



AA-CR-175-2137-8. Outboard after leg of the starboard gun tub at frame 73, on 02 level. Note that deck is pulled up by leg.

USS NEVADA (BB36)

Page 49 of 139 Pages




AA-CR-79-1935-12. Topside p otograph looking down and aft from foremast. Lower end of mainmast can be seen still in place. Upper section hanging down, held only by electrical wiring. Note damage to supports of magnesyn compass transmitter mounted on mast.

SECRET

USS NEVADA (BB36)


Page 50 of 139 Pages



AA-CR-80-1897-10. After tripod, looking aft showing mainmast and yardarms.


Page 51 of 139 Pages

USS NEVADA (BB36)



AA CR-80-1897-11. After tripod, looking aft and to starboard.

USS NEVADA (BB36)



AA-CR-80-1900-8. Break in fixed portion of mainmast pole.

Page 53 of 139 Pages

USS NEVADA (BB36)



AA-CR-80-1900-7. Break in mainmast pole.

Page 54 of 139 Pages


USS NEVADA (BB36)



BB-CR-80-1911-5. Main battery director platform on mainmast, frame 80, looking forward showing fractured director pedestal.

USS NEVADA (BB36)


Page 55 of 139 Pages



AA-CR-80-1911-8. After AA defense station (mainmast) looking aft from about frame 80 at dished hatch cover.

USS NEVADA (BB36)


Page 56 of 139 Pages



AA-CR-80-1911-1. Looking aft along port side of superstructure deck from frame 80, showing damage to inboard bulkhead of passage.

Page 57 of 139 Pages


USS NEVADA (BB36)



AA-CR-80-1911-3. Looking forward in superstructure deck from frame 93, starboard side, at dished longitudinal bulkhead.

USS NEVADA (BB36)


Page 58 of 139 Pages



AA-CR-80-1909-8. Superstructure looking forward from frame 101 port.

USS NEVADA (BB36)

Page 59 of 139 Pages



AB-CR-175-2154-9. Locking aft and inboard from about frame 86, port side of upper deck. Note damaged wiring trunk and damaged range-finders booth in back ground.

USS NEVADA (BB36)

9545

Page 60 of 139 Pages



AA-CR-62-1832-9. Surfaces shot from starboard beam. Note smoke from fire on superstructre deck, frame 75.

USS NEVADA (BB36)


Page 61 of 139 Pages



AA-CR-65-1742-6. Blast damage to rear of rangefinder booth, turret No. 2.

Page 62 of 139 Pages


USS NEVADA (BB36)



AA-CR-80-1911-2. Damaged rangefinders booth on turret No. 3, looking aft and to starboard from superstructure.

USS NEVADA (BB36)


Page 63 of 139 Pages



AA-CR-80-1909-11. Upper deck looking aft along port side from frame 30 showing mild deck deflections beginning at frame 32.

USS NEVADA (BB36)


Page 64 of 139 Pages



AA-CR-175-2137-6. Looking down, aft, and to starboard from frame 86, at collapsed section in portside of main deck.

USS NEVADA (BB36)

Page 65 of 139 Pages



AA-CR-68-1747-2. Looking aft and inboard from frame 86, port, at collapsed section in main deck.

Page 66 of 139 Pages

USS NEVADA (BB36)



AA-CR-175-2137-7. Looking down and forward at collapsed section in port side of main deck centered at about frame 88.

Page 67 of 139 Pages

USS NEVADA (BB36)



AA-CR-65-1742-10. Caved in deck over machinery access opening, main deck, looking forward from port. The tear has progressed beyond the forward edge of the hatch, frame 88 to about frame 86.

USS NEVADA (BB36)

Page 68 of 139 Pages



AA-CR-175-2136-11. Compartment C-291-1L. Looking forward and to port on second deck at after portion of collapsed main deck (port side of frame 86-91). Note buckled stanchion at frame 91.

Page 69 of 139 Pages

USS NEVADA (BB36)



AA-CR-175-2136-10. Compartment C-291-1L. Looking forward and to starboard on second deck at after portion of collapsed main deck (port side of frames 86-91). Note buckled stanchion at frame 91.

Page 70 of 139 Pages

USS NEVADA (BB36)



AA-CR-175-2137-4. Compartment C-291-1L. Looking aft and outboard at outboard edge of main deck failure (collapsed section, port side, frames 86-91.) Note transverse beam and failures at longitudinal bulkhead.

USS NEVADA (BB36)

Page 71 of 139 Pages



AA-CR-175-2137-3. Compartment C-291-1L. Looking aft from second deck at outboard edge of main deck failure. Collapsed area is on port side, frames 86-91.

Page 72 of 139 Pages

USS NEVADA (BB36)



AA-CR-175-2137-5. Crew's berthing, C-291-1L, second deck, looking inboard along frame 86 at forward extremities of collapsed section on main deck, port side, frame 86-91.

USS NEVADA (BB36)


Page 73 of 139 Pages



AA-CR-175-2137-2. Compartment C-291-1L. Looking forward and to starboard from the second deck at inboard line of failure of main deck beams and deck plating. Collapsed area is on port side, frames 86-91.

USS NEVADA (BB36)


Page 74 of 139 Pages



AA-CR-175-2137-1. Compartment C-291-1L. Looking aft and to starboard from the second deck at inboard line of failure of main deck beams and deck plating. Collapsed area is on port side, frame 86-91.

USS NEVADA (BB36)


Page 75 of 139 Pages



AA-CR-175-2136-12. Compartment C-291-1L. Looking forward on second deck along inboard edge of collapsed section of main deck (port, frames 86-91).

Page 76 of 139 Pages


USS NEVADA (BB36)



AA-CR-80-1911-7. Topside photograph looking down and aft from main-mast structure level.

Page 77 of 139 Pages

USS NEVADA (BB36)



AA-CR-80-1893-10. Looking inboard from starboard side of the main deck at frame 110.

Page 78 of 139 Pages


USS NEVADA (BB36)



AA-CR-80-1909-3. Main deck looking forward along port side from frame 138. Note ridge in deck at bulkhead 132 (below deck).

Page 79 of 139 Pages


USS NEVADA (BB36)



AA-CR-79-1935-2. Main deck, looking forward and to starboard from about frame 135 at centerline showing plane wreckage and general debris.

Page 80 of 139 Pages

USS NEVADA (BB36)



AA-CR-80-1909-2. Main deck looking forward and to starboard from about frame 138 near centerline after cleaning up. Note deck deflection and ridge with fractured wooden deck covering at bulkhead 132. (below deck).

SECRET.

USS NEVADA (BB36)

SECRET Page 81 of 139 Pages



AA-CR-80-1909-6. Looking forward along the centerline of the main deck from frame 127. Note deck deflection forward from bulkhead 122. (below deck) Turret No. 4 is in background.

USS NEVADA (BB36)

Page 82 of 139 Pages



AA-CR-79-1935-5. Looking to starboard on main deck at after side of turret No. 4. Note deck pulled away from barbette, frame 116 1/2.

USS NEVADA (BB36)

Page 89 of 139 Pages



AA-CR-65-1743-2. Burned area of wood deck which was covered by burned canvass, upper deck, frame 9, starboard.

Page 84 of 139 Pages

USS NEVADA (BB36)



AA-CR-65-1743-1. Fire damage to wood deck, frame 21, near port rail.

Page 85 of 139 Pages


USS NEVADA (BB36)



AA-CR-65-1742-11. Burned canvas on upper deck, frame 39, port.

Page 86 of 139 Pages

USS NEVADA (BB36)



AA-CR-65-1817-1: Burned area on main deck, frame 144, starboard, under burned coil of line.

Page 87 of 139 Pages

USS NEVADA (BB36)




AA-CR-80-1900-5. Superstructure, looking forward from port side of main deck from frame 98. Note port quarter deck boom thrown upward and bent.

SECRET

USS NEVADA (BB36)


Page 88 of 139 Pages



AA-CR-100-1889-7. Port cargo boom at frame 85 1/2, showing bend in boom and location of boom after Test A.

Page 89 of 139 Pages

USS NEVADA (BB36)



AA-CR-100-1889-5. End fitting of port cargo boom, frame 85 1/2. Looking inboard and forward. Note twist in fitting.

USS NEVADA (BB36)

Page 90 of 139 Pages



AA-CR-100-1889-8. Port side ladder davit, frame 105, showing bend above deck edge fitting.

Page 91 of 139 Pages


USS NEVADA (BB36)



AA-CR-80-1893-9. Superstructure from starboard quarter.

Page 92 of 139 Pages

USS NEVADA (BB36)



AA-CR-80-1909-5. Looking inboard from starboard side of main deck at frame 128 showing catapults.

Page 93 of 139 Pages


USS NEVADA (BB36)



AA-CR-100-1889-9. Stern crane, showing lower section buckled and resting on the catapult. Looking aft and to starboard.


Page 94 of 139 Pages

USS NEVADA (BB36)



Page 95 of 139 Pages

USS NEVADA (BB36)



AA-CR-100-2198-1. View of stern crane backstay.

Page 96 of 139 Pages


USS NEVADA (BB36)



AA-CR-100-1889-12. Detail of failure of lower section of crane.

Page 97 of 139 Pages


USS NEVADA (BB36)



AA-CR-175-2154-4. Crew's space. A-0114L. Stanchion 16 feet off centerline at frame 66, upper deck level, starboard side, looking inboard, showing tripping of beam and deformation of stanchion.


USS NEVADA (BB36)

Page 98 of 139 Pages



AA-CR-175-2154-8. Crew's space. A-0114L. Stanchion (16 feet off centerline) at frame 66, upper deck level, port side, showing tripped beam and split stanchion.


USS NEVADA (BB36)



AA-CR-175-2137-12. Crew's space. A-0114L. Upper deck level, frame 68. Starboard leg of forward tripod, looking aft showing crumple in flange of longitudinal and slight dish in leg at this point.

USS NEVADA (BB36)

Page 100 of 139 Pages



AA-CR-175-2154-3. Crew's space. A-0114L. Upper deck level. Port leg of forward tripod looking aft and slightly outboard, frame 69, showing crumple in lower flange of longitudinal and slight dish in leg.

USS NEVADA (BB36)

Page 101 of 139 Pages



AA-CR-175-2137-9. Port leg of forward tripod, frame 69, looking aft, showing crack in leg just above weld, superstructure deck level.

USS NEVADA (BB36)

Page 102 of 139 Pages



AA-CR-175-2154-2. Crew's space. A-0114L. Upper deck level. Forward leg of port director tub, frame 68-69, looking up and slightly outboard.

USS NEVADA (BB36)

Page 103 of 139 Pages



AA-CR-175-2154-1. Crew's space. A-0114L. Upper deck level. Forward leg of port director tub, frame 68-69, looking inboard, showing compression evidence at top of leg.

USS NEVADA (BB36)

Page 104 of 139 Pages



AA-CR-175-2137-10. Crew's space. A-0114L. Upper deck level. Forward leg of starboard director tub, frame 68-69, looking inboard and slightly aft. Showing compression evidence at top of leg and twist in beam at frame 68.

SECRET

USS NEVADA (BB36)


Page 105 of 139 Pages



AA-CR-175-2137-11. Crew's space. A-0114L. Upper deck level. Forward leg of starboard director tub, frame 68-69, looking aft and outboard. Showing compression evidence at top of leg.

USS NEVADA (BB36)

Page 106 of 139 Pages



SECRET

Page 107 of 139 Pages

USS NEVADA (BB36)



AA-CR-175-2154-5. Crew's space. A-Q114L. Deck beams under 02 level, frames 66, 67 and 68, at longitudinal bulkhead, 8 feet off center-line to starboard, looking aft.

Page 108 of 139 Pages

USS NEVADA (BB36)



AA-CR-80-1910-1. Looking aft and inboard at starboard side of transverse bulkhead 61 on upper deck. Note that overhead has been slightly depressed buckling the bulkhead and door.


USS NEVADA (BB36)



AA-CR-80-1910-3. Looking aft and inboard from frame 78 on starboard side of upper deck.

Page 110 of 136 Pages


USS NEVADA (BB36)



AA-CR-175-2155-5. Wardroom. A-126-L. Looking aft and inboard at indentation punched in main deck by starboard stanchion at frame 25.

Page 111 of 139 Pages

USS NEVADA (BB36)



AA-CR-175-2155-6. Wardroom. A-126-L. Local deflection of main deck in way of port stanchion, frame 28, looking forward and inboard.

USS NEVADA (BB36)


Page 112 of 139 Pages



AA-CR-175-2155-7. Wardroom. A-126-L. Local deflection of main deck in way of centerline and port stanchion, frame 28.

Pa_3 113 of 139 Pages

USS NEVADA (BB36)



USS NEVADA (BB36)



AA-CR-175-2136-6. Crew's berthing, D-201-4L, 2nd deck. Looking to port from centerline at buckle in aft face of bulkhead 97.

USS NEVADA (BB36)

Page 115 of 139 Pages



AA-CR-175-2136-9. Crew's berthing, C-291-1L, 2nd deck, looking to port at frame 93, at damage to transverse beams under the main deck and to port stanchion.

USS NEVADA (BB36)

Page 116 of 139 Pages

9545,



AA-CR-175-2136-4. Compartment C-291-1L. Looking forward and to port on second deck at damaged ventilation duct through starboard side of bulkhead 85.

USS NEVADA (BB36)




AA-CR-175-2136-3. Crew's berthing, D-203-1L, 2nd deck, looking at port face of centerline bracket connecting main deck girder to after face of No. 4 barbett frame 116 1/2.

USS NEVADA (BB36)


9545

Page 118 of 139 Pages



AA-CR-175-2136-2. Crew's berthing, D-203-1L, 2nd deck, frames 115 to 122, looking aft along starboard stanchions.

USS NEVADA (BB36)



AA-CR-175-2136-5. Crew's berthing. C-291-1L, 2nd deck. Damage to joiner bulkhead framing, starboard side of pantry, frames 87 1/2 to 94, looking aft and to port.

USS NEVADA (BB36)


Page 120 of 139 Pages



AA-CR-175-2136-8. Tailor shop (ex-library), C-291-1L, 2nd deck, damage to light joiner bulkhead, frames 94 to 97 looking to starboard from centerline.

USS NEVADA (BB36)

Page 121 of 139 Pages



AA-CR-175-2136-7. Quick acting watertight door, in port side of bulkhead 97, looking forward and to port. Door is buckled aft 3 1/2 inches.


USS NEVADA (BB36)

Page 122 of 139 Pages



AA-CR-80-1910-4. Damaged ventilator trunk on superstructure deck at frame 87, starboard side. Ships force repair had been made when picture was taken.

USS NEVADA (BB36)



AA-CR-82-1830-8. Looking forward on port side of navigation bridge at damage to port alidade pelorus stand.

USS NEVADA (BB36) Page 124 of 139 Pages



AA-CR-65-1743-10. Typical paint scorching - boat deck, amidships, starboard side.

USS NEVADA (BB36)


Page 125 of 139 Pages



AA-CR-65-1743-6. Damage to paint on face of a bulkhead facing forward.

USS NEVADA (BB36)
9545

Page 126 of 139 Pages



AA-CR-80-1909-1. Looking forward on starboard quarter, note uncharred outline of airplane catapult and manila line.

USS NEVADA (BB36)

Page 127 of 139 Pages



AA-CR-62-1875-7. No. 6 boiler, left side casing panel.

Page 128 of 139 Pages

USS NEVADA (BB36)



AA-CR-62-1875-8. No. 5 boiler, right side casing panel.

USS NEVADA (BB36)

Page 129 of 139 Pages




AA-CR-62-1876-1. No. 4 boiler, rear wall near steam drum and tubes.

USS NEVADA (BB36)

Page 130 of 139 Pages




AA-CR-62-1876-2. No. 4 boiler, rear wall near sidewall, right.



AA-CR-62-1875-11. Upper after port side of stack.

Page 132 of 139 Pages


USS NEVADA (BB36)
9545



AA-CR-62-1875-12. Upper part of stack, forward starboard side showing damage to stack and stack cowling.

USS NEVADA (BB36)


Page 133 of 139 Pages



AA-CR-62-1875-10. Stack base, port side, showing torn plate.

Page 134 of 139 Pages


USS NEVADA (BB36)



AA-CR-82-1830-4. Port 36 inch searchlight showing the damage to the light and the trunnion arms. Looking forward.

USS NEVADA (BB36)


Page 135 of 139 Pages



AA-CR-82-1830-5. Port 36 inch searchlight showing the damage to the shutter and front door. Looking to port.

USS NEVADA (BB36)


Page 136 of 139 Pages



AA-CR-82-1830-10. Showing the starboard 24 inch searchlight. Glass blown out. Looking forward.

Page 137 of 139 Pages


USS NEVÁDA (BB36)



AA-CR-82-1830-11. Showing the damage to the port 24 inch search-light. Looking aft.

Page 138 of 139 Pages

USS NEVADA (BB36)



A-CR-30 1911-4. Control dials for the port 36 inch searchlight torn from its rounting by the air blast. Show at frame 60 on the superstructure deck.

Page 139 of 139 Pages

CONFIDENTIAL

USS NEVADA (BB36)



Defense Special Weapons Agency 6801 Telegraph Road Alexandria, Virginia 22310-3398

10 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER ATTENTION: OMI/Mr. William Bush

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency (formerly Defense Nuclear Agency) Security Office has reviewed and declassified the following reports:

AD-366718	XRD-32-Volume	3	
AD-366726~	XRD-12-Volume	2	
AD-366703	XRD-16-Volume	1	
AD-366702	XRD-14-Volume	2	
AD-376819L″	XRD-17-Volume	2	
AD-366704~	XRD-18		
AD-367451	XRD-19-Volume	1	
AD-36670 55-	XRD-20-Volume	2	AD-366705
AD-376028L~	XRD-4		
AD-366694 -	XRD-1		
AD-473912 ~	XRD-193		
AD-473891-	XRD-171		
AD-473899	XRD-163		
AD-473887-	XRD-166		
AD-473888 -	XRD-167		
AD-473889 -	XRD-168		

SUBURCI: Declassification of Reports	SUBJECT:	Declassification	of	Reports
--------------------------------------	----------	------------------	----	---------

AD-B197749	XRD-174			
AD-473905 ~	XRD-182	RD-182		
AD-366719	XRD-33 Volu	ıme	4	
AD-366700	XRD-10			
AD-366712-	XRD-25 Volu	ıme	1	
AD-376827L-	XRD-75			
AD-366756 *	XRD-73			
AD-366757-	XRD-74			
AD-366755 '	XRD-72			
AD-366754~	XRD-71			
AD-366710~	XRD-23 Volu	ıme	1	
AD-366711-	XRD-24 Volu	ıme	2	
AD-366753	XRD-70			
AD-366749	XRD-66			
AD-366701-	XRD-11			

All of the cited reports are now approved for public release; distribution statement "A" applies.

AD-366745 XRD-62.

Andith Jarrett arrett

Chief, Technical Resource Center

copy furn: FC/DSWA (DASIAC)

KSC